



REFERENCE NO: RF-13-04

DATE: April 4, 2013

SUBJECT: 2010-2013 MAZDA3 - Steering Gear Missing Heat Shield Bolt Holes

As a running change, the heat shield bolt holes have been eliminated from the latest steering gear part numbers shown below (new & remanufactured).


If a replacement steering gear is received without bolt holes for the heat shield, the heat shield will not need to be reinstalled. NOTE: Heat shields do not come with old or new style steering gears.

- BBM4-32-110
- BBM4-32-110B
- BBM4-32-110A
- BBM4-32-110C
- BBM4-32-110R-0C

**OLD STYLE (WITH MOUNTING HOLES FOR HEAT SHIELD)**



**NEW STYLE (NO MOUNTING HOLES FOR HEAT SHIELD)**



**Tony Lawrence**

---

**From:** Chris Ciz  
**Sent:** Thursday, April 04, 2013 2:50 PM  
**Subject:** Mazda Parts Flash

### **Parts Flash Release – April 4, 2013**

For a printable PDF file from MStore, please click on the link below each title

#### **Parts Flash Index**

[http://www.mstore2000.com/PDF\\_Files/PartsFlashIndex04-04-13.pdf](http://www.mstore2000.com/PDF_Files/PartsFlashIndex04-04-13.pdf)

The following Parts Flash is new:

**2010-2013 MAZDA3 - Steering Gear Missing Heat Shield Bolt Holes**

[http://www.mstore2000.com/PDF\\_Files/13-04.pdf](http://www.mstore2000.com/PDF_Files/13-04.pdf)

The following Parts Flash is revised:

**2013 CX-5 - Accessory Navigation Kit Application (KD37-79-EZX)**

[http://www.mstore2000.com/PDF\\_Files/13-02R1.pdf](http://www.mstore2000.com/PDF_Files/13-02R1.pdf)